




Logitech K830 Repair USB connector Replacement

Written By: mathieubernou



Step 1 — Repair USB connector



- Turn the keyboard. Back facing up

Step 2



- Remove the 4 rubers hiding 4 screws

Step 3



- Unscrew the 8 visible screws

Step 4



- Unclip the two plastic side of the keyboard



Careful the maximum opening distance range is limited by an internal connection. Open gently

Step 5



- Unplug the connection avoid the separation of the two plastic parts.

Step 6



- Unplug the batterie connector from the base side
- You can now separate the two part of the keyboard

Step 7



- Repair the welding of the micro usb connector

Step 8



- Plug the battery connector

Step 9



- Plug the connection from the upper part of the keyboard

Step 10



- Reassemble both keyboard part
- Clip them together

Step 11



- Screws the 8 screws

Step 12



- Stick the 4 rubers at their respectives positions

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-20 03:53:33 AM.